Release Notes

EWS377APv3

Ver. v3.9.3_c1.9.51

Revision History

Revision	Date	Reason of Changes
v3.9.3_c1.9.51	Dec 27, 2021	Fix update

Change Log

Notice: APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v3.9.3_c1.9.51
Type	Description
New Feature	N/A.
Change	N/A
Fix	1. Fix SNMP get Wi-Fi client list fail. 2. Fix ezMaster Active Client list (Name/IP/OS) is null. 3. Fix mesh slave cannot connect to mesh root when L2 isolation is enabled. 4. Fix XSS vulnerabilities issue for input special SSID. 5. Fix fragment and forge vulnerabilities issue.