

# ECB-3220/EOC3220 Change Log

**Release Date March 26, 2009**

Firmware : 1.43.05	HW Version : 1.1.0
-----------------------	--------------------

## Changed

- Modify PPPoE does not redial after a disconnection

**Release Date Feb 16, 2009**

Firmware : 1.43.04	HW Version : 1.1.0
-----------------------	--------------------

## Changed

- WDS enabled , hidden Universal Repeater button
- Universal Repeater enabled, disable WDS button

**Release Date Aug 13, 2008**

Firmware : 1.43.03	HW Version : 1.1.0
-----------------------	--------------------

## Changed

- boot code is added to support spansion flash ID code

**Release Date July 24, 2008**

Firmware : 1.43.02	HW Version : 1.1.0
-----------------------	--------------------

## Changed

- When flash current setting error , we use current setting backup to recover it
- modify web error