

Release Notes

EAP350

Ver. 1.6.43

Revision History

Revision	Date	Reason of Changes
V1.6.43	Jun 18, 2015	Fix and change update

Change Log

F/W Version	V1.6.43
Type	Description
New Feature	N/A
Change	1. Default setting update
Fix	1. Fix CLI bug when modifying device name by CLI, the following OIDs should be updated as well upon AP reboot. 1.3.6.1.4.1.14125.2.1.1.1.0 1.3.6.1.2.1.1.5.0