Release Notes

EWS510AP

Ver. v2.0.300_c1.8.57

Revision History

Revision	Date	Reason of Changes
V2.0.300_c1.8.57	Nov 24, 2017	Fix update

Change Log

Notice: APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.8 software.

F/W Version	V2.0.300_c1.8.57	
Туре	Description	
New Feature	N/A	
Change	N/A	
Fix	1. Fix WPA2 vulnerability issue.	