

Release Notes

EWS357APv2

Ver. v3.9.3_c1.9.51

Revision History

Revision	Date	Reason of Changes
v3.9.3_c1.9.51	Dec 27, 2021	Fix update

Change Log

Notice: APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v3.9.3_c1.9.51
Type	Description
New Feature	N/A.
Change	N/A
Fix	<ol style="list-style-type: none">1. Fix SNMP get Wi-Fi client list fail.2. Fix ezMaster Active Client list (Name/IP/OS) is null.3. Fix mesh slave cannot connect to mesh root when L2 isolation is enabled.4. Fix XSS vulnerabilities issue for input special SSID.5. Fix fragment and forge vulnerabilities issue.