

Release Notes

ENH500v2

Ver. V1.5.74

Revision History

Revision	Date	Reason of Changes
V1.5.74	Sep 18, 2015	Bug fix update

Change Log

F/W Version	V1.5.74
Type	Description
New Feature	N/A
Change	N/A
Fix	<ol style="list-style-type: none">1. Fixed the bug when user enabled VLAN ID by SSID, the wireless client is not able to play YouTube.2. Fixed the bug when user enabled VLAN ID by SSID, the TCP data over 1468 will encounter ping loss.