

Release Notes

EWS371AP

Ver. v3.0.0_c1.8.59

Revision History

Revision	Date	Reason of Changes
v3.0.0_c1.8.59	Oct 23, 2017	Change and fix update

Change Log

Notice: APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.8 software.

F/W Version	v3.0.0_c1.8.59
Type	Description
New Feature	N/A
Change	1. Update CAPWAP version to c1.8.59
Fix	1. Fix WPA2 vulnerability issue. 2. Fix dnsmasq vulnerability issue.